

INFORMATION TECHNIQUE

Réfrigérateurs combinés ventilés

Modèles : ERCV180-55B1, ERCV180-55V1, ERCV180-55B2, ERCV180-55V2

Codes : 8008147, 8008148, 8008700, 8008701

Marque : EssentielB

Défaut : Froid excessif dans la partie réfrigérateur (produits dans le bac à légumes qui gèlent), froid insuffisant


Cause possible : Mauvais réglage du volet de répartition du froid dans la partie congélateur

Solution : Mettre le réglage du volet tout à gauche :



Position max pour ERCV180-55b1 et ERCV180-

55v1.



Position max pour ERCV180-55b2 et ERCV180-

55v2.

Cela va réduire l'apport d'air froid dans la partie réfrigérateur et laisser le froid dans le congélateur.

SAV. Nos Marques.

TECHNICAL INFORMATION

Models : ERCV180-55B1, ERCV180-55V1, ERCV180-55B2, ERCV180-55V2


Codes : 8008147, 8008148, 8008700, 8008701

Brand : EssentielB


Fault : Excessive cold in the refrigerator section (products in the vegetable drawer freezing), insufficient cold

Possible cause : Incorrect adjustment of the cold repartition shutter in the freezer section

Solution : Set the shutter setting to the far left :



Position max pour ERCV180-55b1 et ERCV180-



Position max pour ERCV180-55b2 et ERCV180-

This will reduce the supply of cold air to the refrigerator section and leave the cold in the freezer.

SAV. Nos Marques.